

Assignment name: Structural integrity check and prepare drawing and BOQ for an additional floor on existing Cox's Bazar EPI center for nutrition sector office.	Country: Bangladesh. Location within country:
Name of Client: UNICEF	Address: BSL Office Complex, 1 Minto Road, Dhaka 1000, Bangladesh.
Duration of assignment (months): 2 Start date (month/year): 23.01.2020 Completion date (month/year): 05.03.2020	Total No of staff-months of the assignment: 160
Approx. value of the contract (in current BDT):	
Name of associated Contractors, if any:	No of professional staff-months provided by associated Contractors:
Name of associated Contractors, if any:	Name of senior professional staff of your firm involved and functions performed (indicate most significant profiles such as Project Director/Coordinator, Team Leader etc): A T M Zaheed Islam, Md. Shajal Khan, Khandaker Mahedi Hasan, Asif Amir, Md. Ashraful Islam
Narrative description of Project: The main objective was to provide site assessment, architectural & structural design and supervision, monitoring & quality control support to do the construction of one additional floor on the existing Cox's Bazar EPI store for nutrition sector office.	
Description of actual services provided by your staff within the assignment: <ul style="list-style-type: none"> ➤ Site assessment and structural integrity check ➤ Check the structural integrity of existing structures by detail structural assessment for vertical extension ➤ Check existing electrical connection capacity for the proposed extension ➤ Detail drawing of the existing structure ➤ Detail structural assessment report ➤ Prepare architectural, structural and electrical drawing for the additional floor ➤ Prepare detail BOQ for the proposed expansion ➤ Complete construction drawing for the additional floor 	